
ATIS
128.0
REGIONAL TOWER ★
126.0 (CTAF) 239.0
GND CON
120.2
CLNC DEL
120.2 (WHEN TWR CLSD)
D
VAR 1° W
JANUARY 2010
ANNUAL RATE OF CHANGE
0.1° W
8099 X 150
294°
ELEV
526
A5
A9
A4
A3
A2
A1
A
HIRL Rwy 11-29
MIRL Rwy 17-35
REIL Rwy 11
CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.
FIELD
ELEV
544
6500 X 100
354°
ELEV
542
35
B4
B3
B2
B1
B
ELEV
533
17
C1
174°
114°
11
C
ELEV
538
HS 1
HS 2
FBO
NORTH
HANGARS
FLIGHT
SCHOOL
TWR
FIRE
STATION
ADMINISTRATION
SOUTH
HANGARS
17
21
18
61
63
64
65
66
67
70
RWY 11-29
PCR 440 F/D/X/T
S-106, D-144, 2D-198, 2D/2D2-575
RWY 17-35
PCR 180 F/D/X/T
S-47, D-63, 2D-109
38°53.5'N
38°53.0'N
90°03.5'W
90°03.0'W
90°02.5'W
90°02.0'W
90°01.5'W