



25219

ILS or LOC RWY 27
PIKE COUNTY/HATCHER FLD (PBX)

MISSED APPROACH: Climb to 4500 direct CILOM and hold, continue climb-in-hold to 4500.

UNICOM
122.8 (CTAF) **L**

A diagram of a bent beam. The beam is divided into two segments. The left segment is horizontal and has a length of 53.56 X 100. It is supported by a pin support at the left end and a roller support at the right end. A star is located on the horizontal segment. The right segment is inclined upwards and has a length of 34.55 X 75. The angle between the two segments is 274°. The beam is labeled with '0.3% UP' at both ends. A star is also located on the inclined segment.



CATEGORY	A	B	C	D
S-ILS 27	1722-1 259 (300-1)			
S-LOC 27	2080-1 617 (700-1)		2080-1 $\frac{3}{4}$ 617 (700-1 $\frac{3}{4}$)	
CIRCLING	2120-1 655 (700-1)	2180-1 715 (800-1)	2180-2 715 (800-2)	2460-3 995 (1000-3)

PIKE COUNTY/HATCHER FLD (PBX)
ILS or LOC RWY 27

SE-1, 06 AUG 2026 to 03 SEP 2026